

Recording Requested By and  
When Recorded mail to:

Surveyor's Office  
City of Riverside  
3900 Main Street  
Riverside, Ca 92522



S	R	U	PAGE	SIZE	DA	MISC	LONG	RFD	COPY
			3						4
M	A	L	465	426	PCOR	NCOR	SMF	NCHG	EXAM

21  
07

**CERTIFICATE OF CORRECTION**  
(Monument Substitution)



I, David E. Coryell, certify that I am a Registered Civil Engineer of the State of California; that Tract Map 31360 was prepared by Matthew E. Webb, L.S. 5529, and is filed in Book 392 of Maps, Pages 43 through 47, inclusive, Records of Riverside County, California, and that the following corrections to said map are made by me in accordance with Chapter 3, Article 7, Sections 66469 through 66472 of the Subdivision Map Act.

I am the substitute Registered Civil Engineer replacing the preparer of the map and assuming responsibility for placement of final monuments in accordance with Chapter 3, Article 7, Section 66498 of the Subdivision Map Act. I hereby certify that a survey was performed by me or under my direction on January 5, 2005, retracing or verifying the information contained on said Map, and that said survey was true, complete and sufficient to enable my placing monuments of the character and occupying the positions indicated with the following changes:

**INCORRECT DATA**

Surveyor's Notes:

- 4. ○ INDICATES SET 1" IRON PIPE W/ PLASTIC PLUG STAMPED LS 5529, FLUSH.
- 5. Δ INDICATES SET SPIKE AND TAG, FLUSH, ON STREET CENTERLINES STAMPED LS 5529.
- 12. SET 1" IRON PIPE WITH PLASTIC PLUG STAMPED LS 5529, FLUSH, AT ALL REAR LOT CORNERS, CORNER CUT BACKS AND ANGLE POINTS. WHERE CONCRETE BLOCK WALLS EXIST SET NAIL AND TAG LS 5529 UP 12" ON TOP REAR BLOCK WALL IN LIEU OF 1" IRON PIPE AT REAR LOT CORNERS.
- 13. SET STEEL PIN AND TAG LS 5529 IN TOP OF CURB AT ALL SIDE LOT LINES PROJECTED.

Individual Monuments on said Subdivision Map are incorrect as follows:

- A. *The Centerline Intersection of Lurin Avenue and east Tract Boundary.* -Found 1 1/2" I.P., flush, No Tag
- B. *The Centerline Intersection of Lurin Avenue and Taft Street.* -1" Iron Pipe with Plastic Plug stamped LS 5592, Flush.

CC-204

**CORRECT DATA**

Surveyor's Notes:

- 4. ○ INDICATES SET 1" IRON PIPE WITH PLASTIC PLUG STAMPED "R.C.E 31574", FLUSH.
- 5. Δ INDICATES SET SPIKE AND TAG, FLUSH, ON STREET CENTERLINES STAMPED "R.C.E. 31574".
- 12. SET 1" IRON PIPE WITH PLASTIC PLUG STAMPED "R.C.E. 31574", FLUSH, AT ALL REAR LOT CORNERS, CORNER CUT BACKS AND ANGLE POINTS. WHERE CONCRETE BLOCK WALLS EXIST SET NAIL AND TAG "R.C.E. 31574" ON TOP OF REAR BLOCK WALL IN LIEU OF 1" IRON PIPE AT REAR LOT CORNERS.
- 13. SET STEEL PIN AND TAG "R.C.E. 31574" IN TOP OF CURB AT ALL SIDE LOT LINES PROJECTED.

Individual Monuments on said Subdivision Map are correct as follows:

- A. *The Centerline Intersection of Lurin Avenue and east Tract Boundary.* -Set spike and washer, R.C.E. 31574, Flush.
- B. *The Centerline Intersection of Lurin Avenue and Taft Street.* -Set spike and washer, R.C.E. 31574, Flush.

There are no fee property owners affected by this correction.

Dated: 4-30-09




David E. Coryell  
R.C.E. 31574  
License Expires 12/31/10



**CITY SURVEYOR'S CERTIFICATE**

This Certificate of Correction has been examined by the undersigned and such examination disclosed that the only change(s) shown are in conformance with Section 66469 (a) through (f) of the Subdivision Map Act and Title 18 (Subdivision Ordinance) of the City of Riverside Municipal Code.

Dated: 5/12/09



MARK S. BROWN, City Surveyor  
L.S. No. 5655  
License Expires 9/30/09



2009-0277916  
06/02/2009 08 00A  
3 of 3

101-6

CC-204