

145164

Recording Requested By
and
When Recorded Mail To:

City of Riverside
3900 Main Street
Riverside, CA 92522
Attn: City Engineer

RECEIVED FOR RECORD
1 Min. Past 2 o'clock PM

MAY 22 1987
Recorded in Official Records
of Riverside County, California
William E. Spawley
RECORDER
Fees 3

CERTIFICATE OF CORRECTION

I, Curtis E. Hawkins, certify that I am a Licensed Land Surveyor of the State of California:

That Final Map No. 20586 was prepared by Curtis E. Hawkins L.S. 3163 and is filed in Book 152, Page 33 thru 35 of Maps, Records of Riverside County, California, and that the following corrections to said map are made by me in accordance with Chapter 3, Article 7, Section 66469 thru Section 66472 of the Subdivision Map Act.

That the following data shown on said Final Map is incorrect as:

Surveyor's Notes

Set 3/4" iron pipe with L.S. 3163 tag, set flush at all rear lot corners, unless otherwise noted.

and is corrected as follows:

Surveyor's Notes

No monumentation shall be set for rear lot corners.

There are no fee property owners affected by this correction.

Dated: February 23, 1987

Curtis E. Hawkins
Curtis E. Hawkins, L.S. 3163

State of California
County of Riverside

On 5-14-87, before me, the undersigned, a Notary Public in and for said County and State, personally appeared known to me to be the person whose name CURTIS E. HAWKINS subscribed to the within instrument and acknowledged that executed the same.

WITNESS my hand and official seal.



My Commission Expires June 26, 1989

Signature Steven H. Espinosa
Notary Public

CITY ENGINEER'S CERTIFICATE

This certificate of correction has been examined by the undersigned and such examination disclosed that the only change shown is in conformance with Section 66469 (a) thru (e) of the Subdivision Map Act and Title 18 (Subdivision Ordinance) of the City of Riverside Municipal Code.

Dated: May 15, 1987

ROBERT C. WALES
Riverside City Engineer

By William D. Gardner
DEPUTY RCE 11405

Please record for the benefit of the City of Riverside
Property Services Manager