


C12231

- FOUND 1-1/4"IP w/PLASTIC PLUG, ILLEGIBLE, & TACK DOWN 0.2' PER CORNER RECORD 10-205, AFTER CONSTRUCTION. REMEASURED TIES 1/7/2010
- FOUND L&T IN TC PER CORNER RECORD 10-205
- FOUND L,T&T (LS 6970 TIE) IN TC PER CORNER RECORD 10-205



DISTANCES SHOWN IN () ARE PER CORNER RECORD 10-205

NOTE: TIES ARE NOT TANGENT OVER UNLESS DESIGNATED BY A Φ SYMBOL. ALL TIES NOT SO SHOWN ARE SWING TIES.

