Recording Requested By and When Recorded Mail to:

City of Riverside 3900 Main Street Riverside, CA 92522 Attn: City Engineer RECEIVED FOR RECOR

CERTIFICATE OF CORRECTION (MONUMENT SUBSTITUTION)

JOSEPH N. BEELER, L.S. 4055 NAME:_

That I am a licensed Land Surveyor of the State of California: That Final Map No. 20231 was prepared by William B. Buck.

L.S. 3599

License No.

and is filed in Book 150, Page 60-64 of Maps, Records of Riverside County, California, and that the following corrections to said map are made by me in accordance with Chapter 3, Article 7, Section 66469 thru 66472 of the Subdivision Map Act.

I am the substitute Land Surveyor replacing the preparer of the map and assuming the responsibility for placement of final monuments, in accordance with Chapter 3, Article 7, Section 66498 of the Subdivision Map Act. I hereby certify that a survey was performed by me or under my direction on February 16, 1988, retracing and/or verifying the information contained on said map, and that said survey was true and complete and sufficient to enable my placing monuments of the character and occupy the positions indicated, with the following changes:

Incorrect Data

Correct Data

Centerline control for Rhinelander Drive; Center of Cul-de-sac for Sturbridge Court and Landmark Court; Intersection of the southeasterly right-of-way of the A.T. & S.F. Railroad and the southwesterly rightof-way of Harrison Street:

Indicates set 3/4" iron pipe with plastic plug stamped "L.S. 3599" flush.

Indicates set 1" iron pipe tagged "L.S. 4055" flush.

2. The intersection of the southeasterly right-of-way of the A.T. & S.F. Railroad and the centerline of Harrison Street:

Indicates set 3/4" iron pipe with plastic plug stamped "L.S. 3599" flush.

Indicates found nail and R.C.F.C. & W.C.D. tag, flush.

3. Most easterly lot corners of Lots 5, 9, 10, 14, 16, 28, 41, 44, 46, 47, and 50; The front lot corners of Lots 19, 20, 33, and 34; The most westerly lot corners of Lots 23 and 38:

Set nail with disc stamped "L.S. 3599" in top of curb at the prolongation of all side lot lines.

Set nail and "L.S. 4055" tag in top of curb at the prolongation of side lot lines.

4. Most easterly lot corners of Lots 20-22 and 24; Rear lot corners of Lots 30 and 47; Most southerly lot corners of Lots 16 and 18:

Set 3/4" iron pipe with plastic plug stamped "L.S. 3599", flush at all rear lot corners and angle points in side lot lines, unless otherwise noted.

Set 1" O.D. iron pipe tagged "L.S. 4055", flush.

5. Most easterly lot corners of Lots 2-4, 6-8, 12, 13, 15, 26, 27, 29, 38-40, 42, 45, 48, 49, and 51; Most westerly lot corners of Lots 18, 21, 22, 24, 26, 31, 32, 35, and 36:

Set nail and tag stamped "L.S. 3599" in top of curb at the prolongation of all side lot lines.

Found nail and "L.S. 4724" tag in top of curb at the prolongation of side lot lines.

Certificate of Correction (Monument Substitution)
Page 2 of 2

6. Most westerly lot corners of Lots 39, 40, 43-45, 48-50; Most easterly lot corners of Lots 18, 19, 23, 25, and 31-37:

Set 3/4" iron pipe with plastic plug stamped "L.S. 3599" flush at all rear lot corners and angle points in side lot lines, unless otherwise noted.

Found 1" O.D. iron pipe tagged "L.S. 4724" flush.

7. Most westerly lot corners of Lots 13-16, and 41; Most westerly rear corner of Lot 20:

Set 3/4" iron pipe with plastic plug stamped "L.S. 3599" flush at all rear lot corners and angle points in side lot lines, unless otherwise noted.

Set nail and "L.S. 4055" tag in top of fence.

8. Most northerly lot corners of Lots 3-6, and 10:

Set nail with disc stamped "L.S. 3599" in South face of wall, 1' below top of rear side lot lines on Lots 1-11.

Set nail and "L.S. 4055" tag in top of fence.

9. Most northerly lot corners of Lots 7-9, and 11:

Set nail with disc stamped "L.S. 3599" in South face of wall, 1' below top of rear side lot lines on Lots 1-11.

Set nail and "L.S. 4055" tag in top of fence.

Most northerly lot corner of Lot 2: 10.

Set nail with disc stamped "L.S. 3599" in South face of wall, 1' below top for rear side lot lines on Lots 1-11.

Set nail and "L.S. 4055" tag SED LAND SURLEY

in face of footing.

There are no fee property owners affected by this correction.

27, 1988 OCTOBER

osych Licensed Land Surve

No. 4055

(Lic. Exp. 6/30/92)

JOSEPH N. BEELER

No. 4055 FOF CALIFOR

State of California (

County of Riverside (ss:

On October 27, 1988 , before me, the undersigned, a Notary Public in and for said County and State, personally appeared Joseph N. Beeler , known to me to be the person whose name

subscribed to the within instrument and acknowledged is executed the same. that he

WITNESS my hand and official seal.

My Commission Expires: May 21, 1990

Donda On Signature:

Notary Public

OFFICIAL SEAL LINDA VI. KING NOVAR ' PUBLIC RIVERSIDE CO. CALIF. tily commission expires 5-21-60

CITY ENGINEER'S CERTIFICATE

This certificate of correction has been examined by the undersigned and such examination disclosed that the only change(s) shown are in conformance with Section 66469 (a) thru (e) of the Subdivision Map Act and Title 18 (Subdivision Ordinance) of the City of Riverside Municipal Code.

1ct. 31, 1988 Dated:

Barry Beck RCE 20900 Riverside City Engineer