

Recording Requested By  
and  
When Recorded Mail to:

City of Riverside  
3900 Main Street  
Riverside, CA 92522  
Attn: City Engineer  
MAP HAS BEEN MARKED WITH  
CERTIFICATE OF CORRECTION  
RECORDING DATA.  
NAME: Russell H. Garner

273058

CERTIFICATE OF CORRECTION  
(MONUMENT SUBSTITUTION)

RECEIVED FOR RECORD  
Min. Past 8 o'clock  
CITY CLERK  
Book 1984, Page 273058

DEC 21 1984

Recorded in Official Records  
of Riverside County, California

*William J. Garney*  
Recorder

certifies

That I am a ~~(Registered Civil Engineer)~~  
(Licensed Land Surveyor) of the State of California:

That ~~(Parcel)~~ (Final) Map No. 19338 was prepared by James F. Davidson Jr.  
L.S. 3018 Name

~~Registration~~/License No.

and is filed in Book 137, Page 39-41 of ~~(Parcel)~~ Maps,  
Records of Riverside County, California, and that the following corrections  
to said map are made by me in accordance with Chapter 3, Article 7, Section  
66469 thru Section 66472 of the Subdivision Map Act.

I am the substitute ~~(Engineer)~~ (Land Surveyor) replacing the preparer of the map and  
assuming the responsibility for placement of final monuments, in accordance  
with Chapter 3, Article 7, Section 66498 of the Subdivision Map Act. I  
hereby certify that a survey was performed by me or under my direction on  
November 21, 1984, retracing and/or verifying the information contained  
on said map, and that said survey was true and complete and sufficient to  
enable my placing monuments of the character and occupy the positions in-  
dicated, with the following changes:

Incorrect Data

- All references on Map (SHEET 3 of 3 SHEETS) to "L.S. 3018".
- All references in "SURVEYOR'S NOTES" (SHEET 3 of 3 SHEETS) to "L.S.3018".

CORRECT DATA

- All references on map (SHEET 3 of 3 SHEETS) to "L.S.3018" is corrected to read "L.S. 3035".
- All references in "SURVEYOR'S NOTES" to "L.S.6. 3018" is corrected to read "L.S.3035".

Correct Data CONTINUED

- The most northerly corner of LOT 2 is marked with a nail and tag L.S.3035, set in the top of a P.C.C. block wall.
- The most easterly corner of LOT 3 is marked with a nail and tag L.S.3035, set in the top of a P.C.C block wall.
- The northerly terminus of that certain course in the northerly boundary of LOT 8 shown as N.34° 22'16"E., 6.00 feet, is marked with a nail and tag L.S.3035, set in the top of a P.C.C.block wall.
- At the southeast corner of LOT 14, I found a 1" I.P., flush, with plastic plug stamped L.S.3018.

There are no fee property owners affected by this correction.

Dated: December 17, 1984

*JH Garner*  
~~(Registered Civil Engineer)~~  
(Licensed Land Surveyor, No. 3035)


State of California : ss  
County of ~~Riverside~~ San Bernardino

On December 17, 1984, before me, the undersigned, a Notary Public in  
and for said County and State, personally appeared Russell H. Garner  
known to me to be the person whose name is subscribed to the  
within instrument and acknowledged that he executed the same.

WITNESS my hand and official seal.

Seal  
My Commission Expires 1/2/88

Signature *Teresa Carr*  
Notary Public  
(Name Typed or Printed)  
Teresa Carr



CITY ENGINEER'S CERTIFICATE

This certificate of correction has been examined by the undersigned and  
such examination disclosed that the only change(s) shown are in conformance  
with Section 66469 (a) thru (e) of the Subdivision Map Act and Title 18  
(Subdivision Ordinance) of the City of Riverside Municipal Code.

Dated: Dec 21, 1984

ROBERT C. WALES  
Riverside City Engineer

Please record for the benefit of the City of  
Riverside  
Property Services Manager

By *Robert C. Wales*

CC-48