

171922

RECORDING REQUESTED BY
AND
WHEN RECORDED MAIL TO:

City of Riverside
3900 Main Street
Riverside, California 92522
Attn: City Engineer

RECEIVED FOR RECORD
AT 9:00 O'CLOCK

APR 26 1994

Recorded in Official Records
of Riverside County, California

Recorder

Fees \$

CERTIFICATE OF CORRECTION

I, James F. Davidson, Jr. certify that I am a Licensed Land Surveyor of the State of California;

That Final Map No. 21875 was prepared by James F. Davidson, Jr., L.S. 3018, and is filed in Book 233, Pages 14 and 15 of Maps, Records of Riverside County, California, and that the following corrections to said map are made by me in accordance with Chapter 3, Article 7, Section 66469 through Section 66472 of the Subdivision Map Act.

That the following data shown on said final map is incorrect as follows:

"MONUMENT LOCATIONS:"

- A. At the Southeast corner of Lot 2; "Set 1" I.P. with plastic plug stamped L.S. 3018, flush."
- B. At the Southwest corner of Lot 4; "Set 1" I.P. with plastic plug stamped L.S. 3018, flush."
- C. At the Southeast corner of Lot 1; "Set 1" I.P. with plastic plug stamped L.S. 3018, flush."
- D. At the Northeasterly terminus of a course which bears N.30°46'15"E., 105.00 feet on the Southeasterly line of Lot 8; "Set 1" I.P. with plastic plug stamped L.S. 3018, flush."
- E. At the Southeasterly terminus of a course which bears N.24°27'21"W., 39.65 feet on the Southeasterly line of Lot 8; "Set 1" I.P. with plastic plug stamped L.S. 3018, flush."
- F. At the Northerly and the Southerly terminus of a course which bears N.05°08'24"W., 201.19 feet on the centerline of Hawarden Drive; "Found 3/4" I.P. with plastic plug stamped L.S. 3163, flush, per MB. 154/33-38."

AND IS CORRECTED AS FOLLOWS:

"MONUMENT LOCATIONS:"

- A. At the Southeast corner of Lot 2; "Set nail and L.S. 3018 tag in concrete footing of blockwall."
- B. At the Southwest corner of Lot 4; "Set nail and L.S. 3018 tag in top of wall pilaster."
- C. At the Southeast corner of Lot 1; "Found 3/4" I.P. tagged RCE 9876, flush."
- D. At the Northeasterly terminus of a course which bears N.30°46'15"E., 105.00 feet on the Southeasterly line of Lot 8; "Set nail and L.S. 3018 tag in rock."
- E. At the Southeasterly terminus of a course which bears N.24°27'21"W., 39.65 feet on the Southeasterly line of Lot 8; "Set nail and L.S. 3018 tag in rock."
- F. At the Northerly and the Southerly terminus of a course which bears N.05°08'24"W., 201.19 feet on the centerline of Hawarden Drive; "Set 1" I.P. with plastic plug stamped L.S. 3018, flush."

There are no fee property owners affected by this correction.

Date: 3-24-94

James F. Davidson, Jr.
 James F. Davidson, Jr.
 Licensed Land Surveyor No. 3018
 Exp. 6-30-96
 No. 3018
 STATE OF CALIFORNIA

State of California)
County of Riverside) ss

171922

On 3/22/94, before me, the undersigned, a Notary Public in and for said County and State, personally appeared James F. Davidson, Jr., known to me to be the person whose name is subscribed to the within instrument, and acknowledged that he executed the same.

WITNESS my hand and official seal.



Signature: Barbara E. Smeltzer
Notary Public in and for
said County and State

CITY ENGINEER'S CERTIFICATE

This Certificate of Correction has been examined by the undersigned and such examination disclosed that the only change(s) shown are in conformance with Section 66469 (a) through (e) of the Subdivision Map Act and Title 18 (Subdivision Ordinance) of the City of Riverside Municipal Code.

Dated: April 21, 1994

BARRY BECK
Riverside City Engineer, R.C.E. 20800

By: Barry Beck