

DOC # 2009-0519253

10/07/2009 08:00A Fee:15.00


Page 1 of 3

Recorded in Official Records

County of Riverside

Larry W Ward

Assessor, County Clerk & Recorder



PLEASE COMPLETE THIS INFORMATION
RECORDING REQUESTED BY

AND WHEN RECORDED MAIL TO

CITY of RIVERSIDE
3900 MAIN ST.
RIVERSIDE, CA 92522
ATTN: CITY ENGINEER

S	R	U	PAGE	SIZE	DA	MISC	LONG	RFD	COPY
1			3						1
M	A	L	465	426	PCOR	NCOR	SMF	NCHG	EXAM
						T	CTY	UNI	002

Space above this line for recorder's use only

TRA:
DTT:

CERTIFICATE OF CORRECTION

16

C
002

Title of Document

THIS AREA FOR
RECORDER'S
USE ONLY

THIS PAGE ADDED TO PROVIDE ADEQUATE SPACE FOR RECORDING INFORMATION
(\$3.00 Additional Recording Fee Applies)

Recording Requested By
and
When Recorded Mail to:

City of Riverside
3900 Main Street
Riverside, California 92522
Attn: City Engineer

CERTIFICATE OF CORRECTION

I, Matthew E. Webb, certify that I am a Licensed Land Surveyor of the State of California; that Final Map No. 31361 was prepared by me and is filed in Book 390, Pages 62-66 of Maps, Records of Riverside County, California; that the following corrections to said map are made by me in accordance with Chapter 3, Article 7, Section 66469 through Section 66472 of the Subdivision Map Act.

That the following data shown on said Final Map is incorrect as:

Surveyor's Notes:

3. ○ INDICATES SET 1" IRON PIPE W/ PLASTIC PLUG STAMPED L.S. 5529, FLUSH.

At the Northwest corner of the Tract boundary at the intersection of the westerly boundary and the Centerline of Krameria Ave., FD. 1" I.P., NO TAG, DN. 0.7'.

At the Southwest corner of the Tract boundary on the Centerline of Lurin Ave., FD. 1" IP W/NAIL & TAG LS 3365, FLUSH, 0.27' WLY. OF CORNER.

and is corrected as follows:

3. ○ INDICATES SET 1" IRON PIPE W/ PLASTIC PLUG STAMPED L.S. 5529, FLUSH, EXCEPT AT THE SOUTHWEST CORNER OF LOT "B", SET RAMSET & TAG, L.S. 5529 ON TOP OF WALL.

At the Northwest corner of the Tract at the intersection of the westerly boundary and the Centerline of Krameria Ave., FD. 1" I.P., NO TAG, DN. 0.7', DESTROYED BY CONSTRUCTION, REPLACED WITH SPIKE AND WASHER, L.S. 5529, FLUSH.

At the Southwest corner of the Tract boundary on the Centerline of Lurin Ave., F. 1" IP W/NAIL & TAG LS 3365, FLUSH, 0.27' WLY. OF CORNER, DESTROYED BY CONSTRUCTION, REPLACED WITH SPIKE AND WASHER, L.S. 5529, FLUSH AT TRACT BOUNDARY LOCATION.

There are no fee property owners affected by this correction.

Dated: 8/31/09

Matthew E Webb

Matthew E. Webb
L.S. 5529
License Expires 9/30/10



CITY SURVEYOR'S CERTIFICATE

This Certificate of Correction has been examined by the undersigned and my examination discloses that changes shown hereon are authorized by and comply with Government Code Section 66469 of the Subdivision Map Act.

Dated: 9/10/09

Mark S. Brown

Mark S. Brown, City Surveyor
L.S. 5655
License Expires 9/30/09